Shop: Lapin Autodiagnostiikka Oy
Tel: +358401449869 Email: myynti@lapinautodiagnostiikkaoy.fi
Address: Teollisuustie 40, Halli 8

Report ID: MAXIA20231123121300
Test Time: 2023-11-23 12:13:00
Technician: --

2013 Mitsubishi Vehicle Diagnostic Report

Vehicle Information

2013 / Mitsubishi / OUTLANDER (GF#) /
VIN: JMBXLGF6WDZ403502

Odometer Reading: 0km
License Plate: IZE-493

Scan to download PDF

Customer Information

Name: --

Device information

Scanner: MaxiSys MS909
Version: V2.81

Serial Number: VA9GNBC01240
Repair Order Number: VA9GNBC01240202311231211192 90

System Scanned (18)

System		Status/DTC
MPI/GDI/Diesel		0
AT/CVT/A-MT/TC-SST		2
ABS/ASC/ASTC/WSS		0
SRS-Air Bag		0
Meter		0
Air Conditioner		0
4WS/Electric Power Steering		0
Lane Keep	ADAS	0
KOS/IMMO/Keyless - IMMOBI & KOS		0
ACC/FCM		2
Steering Angle Sensor		0
AND		0
AUDIO - Display Audio		0
Power Gate		0
AWC		0
OSS		0
CORNER SENSOR/BACK SENSOR		0

ETACS - Selection 105	0

DTC (4)

AT/CVT/A-MT/TC-SST (2 DTCs)

DTC	Description	Status
P1706	Throttle signal malfunction	Stored DTC
P1705	TPS information (Engine)	Stored DTC

ACC/FCM (2 DTCs)

DTC	Description	Status
C1786	System fail detected (T/M)	Stored DTC
C1753	Radar blockage detected	Stored DTC

Technician Notes

ADAS

Customer Name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.